

Welcome



Cheryl Fisher

Educational/
Master Planner



Emily DanisCommunications



Brad Gellert

Project Architect



Planning Timeline

1 10/24/18 Kick-off Meeting

2

10/30/18
Review of the

3

11/7/2018
Develop
Guiding
Principles

4

11/14/2018 Review of HS & MS 5

11/20/2018

Jeopardy Game & Treasurer Report

DATA COLLECTION / IMMERSION

6

11/27/2018 (Tuesday) ★ Master Planning 7

12/5/2018 Master Planning 8

12/12/2018 Master Planning 9

12/18/2018 (Tuesday)★ Master Planning 10

12/26/2018 (change?)

Master Planning

MASTER PLANNING - PUTTING IT ALL TOGETHER



Agenda

Handouts

Guiding Principles

Focus on Middle School Facility Condition

Educational Adequacy – Middle School

Focus on High School Facility Condition

Educational Adequacy – High School

Questions



Agenda

Handouts

Guiding Principles

Focus on Middle School Facility Condition

Educational Adequacy – Middle School

Focus on High School Facility Condition

Educational Adequacy – High School

Questions



Developing Our Guiding Principles





GUIDING PRINCIPLES

State-of-the-Art

Our schools should exhibit high quality construction and instruction supporting academic success and project based learning opportunities. They should be technology rich yet adaptive for future changes.

Community Hub

Our schools should promote a sense of pride among the community and within the buildings, incorporating the rich history and tradition. They should provide an opportunity for community and business partnerships through shared resources.

Safe & Sustainable

Our schools should promote the safety, of students and staff. Features should include, but not be limited to natural light and use of "green" materials.

Collaboration & Flexibility

Our schools should encourage collaboration among students and staff. They should offer flexible spaces and furniture to accommodate small and large groups as well as support a variety of learning styles.



Agenda

Handouts

Guiding Principles

Focus on Middle School Facility Condition

Educational Adequacy – Middle School

Focus on High School Facility Condition

Educational Adequacy – High School

Questions



Wickliffe Middle School – General Information







SF = 92,798 SF

Original Construction: 1920

Additions: 1932 - Addition 1

1963 - Addition 2

2011 - Elevator Addition

Acres: 10.4 acres (total of 14 acres on

MS/ES campus)


Enrollment: 423

Grades 5-8

Building Capacity: 825 students




Wickliffe Middle School – Sequence of Construction








Wickliffe Middle School – Sequence of Construction







Wickliffe Middle School – Sequence of Construction







Wickliffe Middle School –Assessment Validation

	ltem	Rating	S&A 2003 Assessment 2018 Cost Set	October 2018 Desktop Update	Delta:
A	Heating System	3	\$2,851,442.52	\$3,164,107.76	\$312,665.24
	Roofing	3	\$539,560.15	\$551,227.45	\$11,667.30
	Ventilation / Air Conditioning	1	\$0.00	\$0.00	\$0.00
	Electrical Systems	3	\$1,371,357.33	\$1,516,729.44	\$145,372.11
	Plumbing and Fixtures	2	\$679,197.00	\$741,896.00	\$62,699.00
	Windows	3	\$354,445.00	\$0.00	(\$354,445.00)
	Structure: Foundation	1	\$13,000.00	\$112,399.00	\$99,399.00
	Structure: Walls and Chimneys	2	\$17,230.00	\$151,417.50	\$134,187.50
I,	Structure: Floors and Roofs	1	\$0.00	\$0.00	\$0.00
J.	General Finishes	2	\$642,997.20	\$2,738,209.00	\$2,095,211.80
	Interior Lighting	3	\$417,855.00	\$463,990.00	\$46,135.00
L.	Security Systems	3	\$154,606.35	\$296,953.60	\$142,347.25
M.	Emergency/Egress Lighting	2	\$83,571.00	\$92,798.00	\$9,227.00
N.	Fire Alarm	2	\$146,249.25	\$161,924.00	\$15,674.75
Ο.	Handicapped Access	3	\$230,064.20	\$448,105.60	\$218,041.40
Ρ.	Site Condition	2	\$44,829.12	\$257,321.52	\$212,492.40
Q.	Sewage System	1	\$0.00	\$0.00	\$0.00
R.	Water Supply	1	\$0.00	\$0.00	\$0.00
S.	Exterior Doors	2	\$12,000.00	\$0.00	(\$12,000.00)
T.	Hazardous Material	2	\$155,545.00	\$155,545.00	\$0.00
U.	Life Safety	3	\$320,077.20	\$359,603.60	\$39,526.40
٧.	Loose Furnishings	2	\$250,713.00	\$462,640.00	\$211,927.00
W.	Technology	2	\$482,204.67	\$803,630.68	\$321,426.01
	Subtotal:		\$8,766,943.99	\$12,478,498.15	\$3,711,554.16
X.	Construction Contingency / Non Construction Costs		\$2,141,790.72	\$3,048,534.53	\$906,743.82
	Subtotal:		\$10,908,734.71	\$15,527,032.68	\$4,618,297.98
Т	otal Cost (regional cost factor applied (103.60%)):		\$11,301,449.16	\$16,086,005.86	\$4,784,556.70
- N	Master Plan Web Tool Reprogramming Calculation		\$0.00	\$0.00	\$0.00
	Enhanced Reprogramming		\$0.00	\$0.00	\$0.00
	Grand Total		\$11,301,449.16	\$16,086,005.86	\$4,784,556.70



Wickliffe Middle School – Facility Condition



Wood flooring in worn condition



Floor Slab settlement (repair)



Casework in poor condition



Wickliffe Middle School – Facility Condition



Door in worn out condition



Asphalt cracked/poor condition



Railing rusted/bent







Agenda

Handouts

Guiding Principles

Focus on Middle School Facility Condition

Educational Adequacy – Middle School

Focus on High School Facility Condition

Educational Adequacy – High School

Questions



Educational Adequacy



SIZE











	EXISTING SF	OFCC RECOMMENDED SF	DELTA
CLASSROOMS	avg 755	900	-150
KINDERGARTEN	N/A	N/A	N/A
MEDIA CENTER	2,000	1,545	+455
STUDENT DINING	5,500	3,000	+1,500
KITCHEN	1,100	1,803	-703
GYMNASIUM	5,325 (plus aux. @ 4800)	4,000	+1,325
MUSIC	1,845	1,200	+645
SCIENCE	N/A	N/A	N/A



DAYLIGHTING



A

Spaces with Daylight

Spaces without Daylight






DAYLIGHTING



囲


Spaces with Daylight

Spaces without Daylight





SAFETY/SECURITY



- Main office is adjacent to main entrance
- A secure vestibule is present at main entrance
- Corridors generally provide good line of sight for supervision
 some jogs present
- Restroom design does not provide sinks in a common area on the outer portion of the bathrooms so adults can better supervise kids



Wickliffe Middle School – Summary

- The overall renovation cost continues to increase and condition continues to deteriorate.
- Site is tight and has little greenspace or room for expansion (unless encroach on field/track).
- Typical classrooms are undersized compared to State standards and are static. However, nearly all group/assembly type spaces are oversized. Overall, the school is underutilized in terms of capacity.
- The school has a generous amount of daylight all teaching/learning spaces are provided with natural light
- Corridors generally provide good line of site, but there are bends and turns causing visual obstructions. The facility has a secure vestibule entrance for enhanced security control.



Agenda

Handouts

Guiding Principles

Focus on Middle School Facility Condition

Educational Adequacy – Middle School

Focus on High School Facility Condition

Educational Adequacy – High School

Questions



Wickliffe High School – General Information



SF =140,079 SF (does not include Professional Development Center)

Original Construction: 1958

Additions: 1963 - Addition 1

1999 - Addition 2

2013 - Elevator Addition

Acres: 85.2 acres

Enrollment: 436

Grades: 9-12


Building Capacity: 844 students








Wickliffe High School – Sequence of Construction








Wickliffe High School – Sequence of Construction







Wickliffe High School – Sequence of Construction







Wickliffe High School –Assessment Validation

			S&A 2003 Assessment 2018 Cost Set	October 2018 Desktop Update	Delta:
	Item	Rating			
	Heating System	2	\$1,719,957.00	\$4,776,247.48	\$3,056,290.48
	Roofing	3	\$966,799.10	\$1,521,821.90	\$555,022.80
	Ventilation / Air Conditioning	3	\$2,339,471.20	\$0.00	(\$2,339,471.20)
		2	\$2,287,326.36	\$2,273,482.17	(\$13,844.19)
E.		2	\$586,942.00	\$628,638.00	\$41,696.00
F.	Windows	3	\$640,445.00	\$260,000.00	(\$380,445.00)
G.	Structure: Foundation	1	\$0.00	\$29,000.00	\$29,000.00
H.	Structure: Walls and Chimneys	2	\$85,800.00	\$169,952.50	\$84,152.50
I.	Structure: Floors and Roofs	1	\$0.00	\$0.00	\$0.00
J.	General Finishes	2	\$1,116,719.40	\$3,299,954.20	\$2,183,234.80
K.	Interior Lighting	3	\$704,660.00	\$700,395.00	(\$4,265.00)
L.	Security Systems	3	\$275,021.00	\$399,225.15	\$124,204.15
M.	Emergency/Egress Lighting	2	\$140,932.00	\$140,079.00	(\$853.00)
N.	Fire Alarm	2	\$260,155.00	\$244,427.75	(\$15,727.25)
0.	Handicapped Access	3	\$241,336.40	\$434,715.80	\$193,379.40
P.	Site Condition	2	\$94,121.04	\$323,222.68	\$229,101.64
Q.	Sewage System	1	\$0.00	\$0.00	\$0.00
R.	Water Supply	1	\$0.00	\$0.00	\$0.00
S.	Exterior Doors	3	\$73,000.00	\$11,000.00	(\$62,000.00)
T.	Hazardous Material	2	\$169,638.00	\$169,638.00	\$0.00
U.	Life Safety	3	\$528,062.00	\$505,602.80	(\$22,459.20)
V.	Loose Furnishings	2	\$445,980.00	\$698,365.00	\$252,385.00
W.	Technology	2	\$813,177.64	\$1,979,806.04	\$1,166,628.40
	Subtotal:		\$13,489,543.14	\$18,565,573.47	\$5,076,030.33
X.	Construction Contingency / Non Construction Costs	l	\$3,295,535.86	\$4,535,625.30	\$1,240,089.44
	Subtotal:		\$16,785,079.00	\$23,101,198.77	\$6,316,119.77
То	tal Cost (regional cost factor applied (103.60%)):		\$17,389,341.84	\$23,932,841.92	\$6,543,500.08
Ma	aster Plan Web Tool Reprogramming Calculation		\$429,372.73	\$429,372.73	\$0.00
	Enhanced Reprogramming		\$0.00	\$0.00	\$0.00
	Grand Total		\$17,818,714.57	\$24,362,214.65	\$6,543,500.08




Wickliffe High School – Facility Condition



HVAC system requires replacement



Rusted exterior doors



Water infiltration lower level of gym (locker room vicinity)



Wickliffe High School – Facility Condition



Windows have been replaced – good condition



Walks cracked & uneven



Corridor finishes







Agenda

Handouts

Guiding Principles

Focus on Middle School Facility Condition

Educational Adequacy – Middle School

Focus on High School Facility Condition

Educational Adequacy – High School

Questions



Educational Adequacy



SIZE




















	EXISTING SF	OFCC RECOMMENDED SF	DELTA
CLASSROOMS	avg 730	900	-170
KINDERGARTEN	N/A	N/A	N/A
MEDIA CENTER	2,100	1,526	+574
STUDENT DINING	3,600	3,000	+600
KITCHEN	2,045	1,526	+519
GYMNASIUM	8,370	9,300	+930
MUSIC	3,730	3,000	+730
SCIENCE	1,080	1,200	-120




DAYLIGHTING



Spaces with Daylight








DAYLIGHTING Spaces with Daylight

Spaces without Daylight

thendesign architecture



SAFETY/SECURITY



- Main office is adjacent to main entrance
- A secure vestibule is present at main entrance
- Corridors have several jogs which may inhibit visual supervision
- Restroom design does not provide sinks in a common area on the outer portion of the bathrooms so adults can better supervise kids



Wickliffe Middle School – Summary

- The overall renovation cost continues to increase and condition continues to deteriorate.
- Available greenspace makes the site favorable for expansion and /or new construction
- Typical classrooms are undersized compared to State standards and are static. However, nearly all group/assembly type spaces are oversized. Overall, the school is underutilized in terms of capacity.
- The 2nd floor classrooms are provided with daylight but not all 1st floors
- Some corridors provide good line of site, but there are bends and turns causing visual obstructions. The facility has a secure vestibule entrance for enhanced security control.

Agenda

Handouts

Guiding Principles

Focus on Middle School Facility Condition

Educational Adequacy – Middle School

Focus on High School Facility Condition

Educational Adequacy – High School

Questions



Next Steps / Schedule

- Tuesday, November 20th at 6:30 pm
 - Topic: Jeopardy Game Review / Treasurer's Report
- Tuesday, November 27th at 6:30 pm
 - Topic: Master Planning
- Wednesday, December 5th at 6:30 pm
 - Topic: Master Planning

*Reminder: All information is posted on the 'Facilities Master Planning' page on the School District website







